Maryland Historical Trust Maryland Inventory of Historic Properties number: W: 29-50

The bridge referenced herein was inventoried by the Maryland State Highway Administration as part of the Historic Bridge Inventory, and SHA provided the Trust with eligibility determinations in February 2001. The Trust accepted the Historic Bridge Inventory on April 3, 2001. The bridge received the following determination of eligibility.

Eligibility Recommended	MARYLAND HISTORICAL TRUST Eligibility Not RecommendedX
	D Considerations:ABCDEFGNone
Comments:	
Reviewer, OPS:_Anne E. Brude	Date:3 April 2001
Reviewer, NR Program:Peter	. Kurtze Date:3 April 2001

den

Maryland Inventory of Historic Properties Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust

Name and SHA No. M 14 over Watts Branch

Location:
Street/Road Name and Number: Glen Road over Watts Branch
City/Town: Rockville Vicinity X
County: Montgomery
Ownership:State_X_CountyMunicipalOther
This bridge projects over:RoadRailway_X_WaterLand
Is the bridge located within a designated district: yes X no
NR listed districtNR determined eligible districtlocally designatedother Name of District
Bridge Type:
Timber BridgeTruss-CoveredTrestleTimber-and-Concrete
_Stone Arch
Metal Truss
Movable Bridge SwingBascule Single Leaf_Bascule Multiple LeafVertical Lift_Retractile_Pontoon
X Metal Girder X Rolled GirderRolled Girder Concrete Encased Plate GirderPlate Girder Concrete Encased
Metal Suspension
Metal Arch

Metal Cantilever	
Concrete Concrete ArchConcrete SlabConcrete Rigid Frame Other Type Name	Beam

Description:

Describe Setting:

Bridge No. M 14 carries Glen Road east-west over Watts Branch in Montgomery County, Maryland. The area around the bridge is wooded, and is located within 50' of two intersections at both ends of the bridge. At least one residence is visible from the bridge. Overhead utility lines parallel the north side of the bridge.

Describe Superstructure and Substructure:

Bridge No. M 14, was built in 1930 and reconstructed in 1976, is a 34' long single span structure. The bridge consists of a corrugated metal plank deck with an asphalt wearing surface carried by steel stingers supported by two concrete abutments. The bridge has a clear roadway width of 13'-1". The bridge has modern W-beam guardrails.

Roadway drainage is seeping thru the corrugated metal deck causing corrosion to the metal deck and steel beams. Residual section losses to the beam flanges (1/16" on the fascia beams) is evident. The streambed scour has caused about 2' of undermining at the northwest wingwall. The traffic barrier on the southwest and northwest corners of the bridge has been damaged by vehicle impact.

Discuss Major Alterations:

This bridge was rehabilitated in 1976. Between 1991 and 1993 the abutments and wingwalls were replaced.

History:

When Built: 1930 (reconstructed 1976) Why Built: Local transportation needs

Who Built: Unknown

Why Altered: Structural and safety needs

Was this bridge built as part of an organized bridge building campaign: Yes

Surveyor Analysis:

This bridge may have NR significance for association with:

__A Events __Person

__C Engineering/Architectural

Was this bridge constructed in response to significant events in Maryland or local history:

It is unknown whether this bridge was constructed in response to significant events in Maryland or local history.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

It is unknown whether the construction and/or alteration of this bridge has had significant impact on the growth and development of the area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district?

No, this bridge is not located in an area which may be eligible for historic designation.

Is the bridge a significant example of its type?

This bridge is not a significant example of its type.

Does the bridge retain integrity of the important elements described in the Context Addendum?

No, this bridge does not appear to have retained the integrity of its primary character defining elements. An undocumented reconstruction occurred in 1976. An additional reconstruction occurred between 1991 and 1993 when the concrete abutments and wingwalls were replaced.

Should this bridge be given further study before significance analysis is made and Why?

Further research of this bridge is unnecessary. This bridge no longer retains integrity of its character defining elements, and this bridge is not eligible for inclusion on the National Register of Historic Places.

Bibliography:

Greiner, Inc.

1995 Maryland Inventory of Historic Bridges.

Montgomery County

v.d. County Bridge Inspection Files.

Spero, P.A.C. & Company, and Louis Berger & Associates


1994 Historic Bridges in Maryland: Historic Bridge Context.

United States Geological Survey

1965 7.5' Rockville Quadrangle, photorevised 1984.

Surveyor:

Name: Jason D. Moser Date: September 1995
Organization: State Highway Admin. Telephone: (410) 321-2213
Address: 2323 West Joppa Road Brooklandville, MD 21022





Inventory # M:29-50

Name M14-SOUTH GLENGD, OVER WATTS BRAND County/State MONTGOMERY / MD
Name of Photographer TRANK JULIANO
Date 2 45
Location of Negative SHR
Description APPROACH EAST
Number 26 of 36



Inventory # M: 29-50

Name MI4-SOUTH GLEN RO EVER WATTS BRANCH
County/State Montoomery/mo
Name of Photographer FRANK JULIANO
Date 2 95
Location of Negative SHR
Description Enevation Looking South
1 4
Number 29 of 34



Inventory # M: 29-50

Name MIH-SOUTH GLEN RD. OVER WATTS BRANCH
County/State MONTGOMERY / MD
Name of Photographer FRANK JULIANO
Date 2/95
Location of Negative SHR
Description APPROACH WEST

Number 20 of 20



Inventory # <u>M:29-50</u>

Name MIH-SOUTH GLEN RO OVER WARS BRANCH
County/State MONTGOMERY mo
Name of Photographer FRANK JULIANO
Date 2 95
Location of Negative SHR
Description ELEVATION LOOKING MORTH
A
4 - 4
Number 3 of 36